

Confidential

**No.10/V-1/(B-100)/2014-VSI
Government of India**



**Office of JS & CVO
Vigilance Unit, CPWD
Nirman Bhawan, New Delhi-110108**

Dated: 7 August, 2015

To

Sh. Prabhakar Singh,
Chief Engineer, NDZ-I,
CPWD, Nirman Bhawan,
New Delhi-11

Subject: Ensuring removal of malba from roofs of buildings.

Recently, during inspection, while dealing with a complaint case, accumulation of malba on roof was noticed specifically in office buildings, where garbage, old office furniture, packing material of office supplies etc. were left by different offices/allottees and their vendors/suppliers engaged, to provide different services to them. The roofs, to which access is generally not restricted, are generally misused by such occupants of the buildings as a dump yard with the intention of hiding their responsibility for maintaining clean and tidy office premises.

Though, such accumulated garbage for which no body claims responsibility, is on and off removed by the concerned Civil field units of CPWD; but the DG, CPWD has taken a serious note of it; and therefore, desired to issue instructions to the concerned field units to ensure that no malba should be allowed to be collected on roofs, even for a day. The same should be collected on to designated malba collection spots on daily basis, from where it can be disposed off as quickly as possible.

All concerned are therefore, requested to ensure compliance of the instructions.

This issues with the approval of CVO, CPWD.

Sd/-
(J. K. Bansal)
Executive Engineer (V) X
Room No. 432 A-Wing.
Nirman Bhawan, New Delhi
☎ 011- 23061861

Copy to:

All Chief Engineers and field Units Through CPWD Web site.

J. K. Bansal
Executive Engineer (V) X